

April 12, 2016 @ 2:00pm Road Inspection

Supervisors – Dave Anderson, Jimmie Roach and Dave Hauser, clerk A. Anderson meet at the town hall to start the annual road inspection.

Adney Lake Road - Shouldering & hole at the corner of Adney Lake Rd. & Old Bridge Rd.

Whispering Pine Lane – Crack fill as needed.

Old Bridge Road – Crack fill as needed, two areas need patching.

Venture Lane – Crack fill as needed, strip needed south end of street.

Mission Way – Discuss with Anderson Bros. their recommendation

Roberts Road – Patch needed on west side of road, crack fill as needed.

Loon Lake Road – Crack fill as needed, two strips needed.

Fools Lake Road – Crack fill as needed.

Riverview Place – Crack fill as needed, patch work needed.

Mission Cutoff – Discuss with Anderson Bros. resurfacing options.

Morningside Road – R.O.W. Tree trimming needed, crack fill as needed.

Pelican Way – R.O.W. Tree trimming needed, crack fill as needed, patch at 12664.

Pelican Beach Road – Crack fill as needed.

Mission Park Drive – 13688 (2) mole patches, crack fill as needed.

Oak Spur – Crack fill as needed.

Rustic Lane & SW Horseshoe – Make into a ‘T’, crack fill as needed.

SW Horseshoe Lake Road – Crack fill as needed.

Huxtable Point – 29618 Patch in center of road, crack fill as needed.

East Bass Lake Road – Crack fill as needed, sink hole patch.

Ridgewood Lane – Sink hole patch needed.

Ridgewood Drive – Crack fill as needed, couple of strip repairs needed.

Timber Cove – R.O.W. Tree trimming needed road good condition.

Mission Heights – Stripping needed, discuss with Anderson Bros.

East Horseshoe Lake Road – Crack fill as needed, shouldering on ‘S’ curve.

Birchwood Trail – R.O.W. Tree trimming needed, crack fill as needed.

Surfland – Crack fill as needed, R.O.W. tree trimming needed.

Deerwood Trail – Crack fill as needed, possible patch needed.

North Pelican Lane – Crack fill as needed.

Canthook - Pelican Township maintains

Greenwood Lane – 13403 Gopher hole needs patching.

North Horseshoe Lake Road – 13425 Patch hole on shoulder, crack fill as needed.

Respectfully Submitted,

Anna Anderson
Clerk