

April 13, 2017 @ 3:00pm Road Inspection

Supervisors Dave Anderson, Jim Roach, Dave Hauser and clerk A. Anderson meet at the town hall to start the annual road inspection.

- Adney Lake Road** – Class 5 needed for a Turn-around at the end of the road. Good condition.
- Whispering Pine Lane** – Good condition.
- Old Bridge Road** – Cut-out patch needed (1/2 way down).
- Venture Lane** – Good condition. Talk with Crow Wing County about shouldering @ Cty. Rd. 11 & Venture Ln. Street sign needed.
- Deerwood Trail** – Good condition. R.O.W. brushing needed.
- Mission Way** – Repair crack seal.
- Roberts Road** – Good condition. R.O.W. brushing needed.
- Loon Lake Road** – Two different crack seal cut-out replacements needed.
- Fools Lake Road** – Good condition. Street sign needed. There was defacing of public property on the 'End of Road' sign. (Stine/Stino, Dean)
- Riverview Place** – Good condition.
- Mission Cut-Off** – Resurfaced in 2016. Very good condition.
- East Bass Lake Road** – Good condition. R.O.W. brushing needed.
- Timber Cove** – Good condition. R.O.W. brushing needed.
- Mission Heights Road** – Good condition. Class 5 needed at the end of the road to help build back up. Fill needed at #14640 due to wash out.
- Cty. Road 116** – Good condition.
- Ridgewood Lane** – Good condition. Shouldering needed at corner of E. Bass Lake Rd. R.O.W. brushing needed.
- Ridgewood Drive** – Fill needed at #27972, fill needed at the corner of Ridgewood Lane.
- East Horseshoe Lake Road** – Class 5 needed on the 'S' curve. Shouldering as needed.
- Birchwood Trail** – R.O.W. brushing needed. Shouldering needed at the corner of E. Horseshoe.
- Surfland** – Ditch wood needed between #29419 & 29385. R.O.W. brushing needed at cul-de-sac.
- North Pelican Lane** – Good condition.
- Canthook Drive** – Good condition. Street sign needed.
- Greenwood Lane** – Shouldering needed at the corner of Cty. Rd. 3.
- North Horseshoe Lake Road** – Good condition. Shouldering needed at the corner of Cty. Rd. 3.
- Morningside Drive** – Good condition. R.O.W. brushing needed (2nd 1/2 of road).
- Pelican Way** – Good condition. R.O.W. brushing needed.
- Pelican Beach Road** – Good condition.
- Mission Park Drive** – Cut-out patch needed at Cty. Rd. 3, repair hole at #13183.
- Huxtable Point** – Hole repair needed at #29618.
- Southwest Horseshoe Lake Road** – Good condition.
- Oak Spur** – Good condition. Street sign needed at the corner of SW Horseshoe.
- Rustic Lane** – Good condition.

Respectfully Submitted – Anna Anderson, clerk